


**Fig. 1**


- 1 Air blower means
- 2 Main body
- 3 Floor plane
- 4 Inlet port
- 5 Outlet port
- 6 Antiallergenic filter
- 7 Deodorizing filter




BEST AVAILABLE COPY

**Fig. 2**


- 8 Assistant inlet port
- 9 Shield part
- 10 Dust sensor
- 11 Gas sensor




**Fig. 3**



*Fig. 4*




**Fig. 5**




***Fig. 6***


PRIOR ART




**Fig. 7**




**Fig. 8**



**Fig. 9**




**Fig. 10**







**Fig. 11**



**Fig. 12**



**Fig. 13**



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☒ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☒ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**